



Replace existing bad pole
@ 42' south from CL.
Install anchor on pole @ 46'
from CL. Minimum
clearance over CR 52 will
be 22'. Pole at address 915
Lindbergh south