Revised	MN MNI Outotata							cms# 20056145 - HELD					ם ו	
2-10-2020 <b>State</b>		Contractor MN Outstate CenturyLink BSW Order/Maintenance Wol						ls A véla a rimatia ra						
<u> </u>	_					itenance Wo	rk Authoi	rization		- ·	0 1			
Company			ange Name	PIRZIV	INXA					Service	Order#		1573677512	
Work Activity	_	Drop-Buried Copper					Capit	Capital Y			Mainte		N	
Customer Name	<u>Dennis</u>										one#	320	4682242	
Address	30093	83rd St						One Call Ticket#						
City & Zip						Pierz	MN 56364							
Location/Directions	83rd St	& 300th	Ave											
Description of Work or Sp	ecial Inst	ructions		bury 3	pr drop	330ft from ped to	nid nid							
Held Order	Y		Permit:	Υ		Bore:	N			CBR#	3202672777			
Tech Name and Tech #	Mitch N	Nyers AB	53371				Employe	e Contact	#		218-537-	7498		
Sketch	Material/Labor Un				ts		Ī <u>,</u> ,	/0 "		•				
(Include Cntr Line & Pedestal)	Description					Notes	- Footage	Footage/Quantity			Comments			
Cntr Line foota		SEB3-22				plow plcmt	3	30						
D ///		SEB3-22T				hand dig plcmt								
Ped# Parish/County		SEPCUTOVER BM83				d at house								
r arisin county		XXSEB-GL				emp drop			Footage when temp can't be re-used					
Township:	BM61(2	BM61(1.25)SEB				footage								
Section		SEBO PER FT LBR			iber & p	low plcmt								
Range	SEBO P	SEBO PER FT LBR T			iber & h	and dig plcmt plow plcmt								
		BM2(5/8)(8)			Fround R	od								
	Trip Ch	Trip Charge			rip Char ermit									
Nearest cross st.	Permit	Permit 300th Ave					Dist	Plat Page		ny placemen	t within the RC	W requires	a permit	
300th Ave			3	009	3 No	330	ft dro			831	d St			
			Brian Knapek Date		e: Inspected By:		1 2 2 2 2 2							
Originated By: Authorized By: (SRO) Authorized By: (MRO) Email sketch to:  1. Distance of the bury	Brian K	napek		Date: Date: Date:	4/8/20	Inspected B	<i>y</i> :	the nearest	t interse	ection		Date: Date:		