

Revised 2-10-2020	State MN	Contractor MN Outstate	CMS#	20094581 - HELD
CenturyLink BSW Order/Maintenance Work Authorization				
Company	Exchange Name	LTFLMNL		Service Order# vn262258
Work Activity	Drop-Buried Copper		Capital	Maintenance
Customer Name	John Cavanaugh		Phone#	320-632-3242
Address	920 8th st sw		One Call Ticket#	
City & Zip	Little Falls			
Location/Directions				
Description of Work or Special Instructions replace asw with new 3 pr				
Held Order	Y	N	Permit: yes N	Bore: yes N
Tech Name and Tech #	Robert 343		Employee Contact#	320-291-9640
Sketch	Material/Labor Units		Footage/Quantity	Comments
(Include Cntr Line & Pedestal)	Description	Notes		
Cntr Line foot	SEB3-22	BSW-3 & plow plcmt	290	
	SEB3-22T	BSW-3 & hand dig plcmt		
Ped#	f1009	SEPCUTOVER		
Parish/County	BM83	BSW guard at house		
	XXSEB-GL	Remove temp drop		Footage when temp can't be re-used
Township:	t129n	BM61(1.25)SEB	BSW Bore footage	115
Section	19	SEBO PER FT LBR	Fiber & plow plcmt	
Range	r29w	SEBO PER FT LBR T	Fiber & hand dig plcmt	
		SEB6-22	BSW-6 & plow plcmt	
		BM2(5/8)(8)	Ground Rod	
		Trip Charge	Trip Charge	
		Permit	Permit	
Nearest cross st.	Lindbergh Dr		Plat Page	Map#
Originated By:		Date:	Completed By:	Date:
Authorized By: (SRO)		Date:	Inspected By:	Date:
Authorized By: (MRO)		Date:		
Email sketch to:				
1. Distance of the bury in Right-of-Way		3. Distance to the nearest intersection		
2. Distance from the terminal to the centerline		4. Nearest State Hwy mile marker		