



GasService Site Check
16846 Nature Rd
Status: Ready

Inspection Date:	11/07/2022
Inspector:	Kurt Clitty
Service Center:	St. Cloud
Hours/Mileage:	1.5 hrs. / 46.2 mi.
Designer:	Shane Peterson
Work Order #:	16846

Service Type:	Residential	Service Location:	Long Side
Job Site Conditions:	n_a	Length of Service line from Property Line to Gas Meter:	150

Bore Needed:	Yes	Traffic Control Needed:	No
Utilities needing to be Spotted along Bore Route:	No		
Route Obstructions:	No		
Locates Marked:	No	Route Flagged:	Yes
Gas Meter Location Marked:	Yes	Sewer Cleared:	Yes
Will the gas meter need to be vented?	No		
Developer Name:	Home owner	Date of Site Readiness:	11/07/2022
Length of Service Lines:	250	Is site within 6" of Final Grade:	Yes
Designer Comment:			



Gas meter location flagged left side of house



Bore required

