

An aerial photograph showing a road intersection. A road labeled '17' runs vertically. A road labeled '100th St' runs horizontally, intersecting the vertical road. Another road labeled 'Cannon Rd' runs vertically, intersecting '100th St' from the bottom. To the left of the vertical road '17', there is a grassy area with trees and a small building. An orange arrow points to a utility pole in this area. A pink text box is overlaid on the image, providing instructions for replacing a bad pole. The image is dated '1991' in the bottom left corner and has a copyright notice '© 2016 G' in the bottom right corner.

Replace bad pole 42' west  
of CL & 485' north of 100th  
st. Minimum height of wire  
along road is 22'  
Pole in on CR 225

100th St

Cannon Rd

17